



SHN06

NEGATIV-NEGATIVE PLANFRÄSER – SCHAFT INSERTS FOR NEGATIVE FACE MILLS




HNGX 06




XNGX 06




HNGX 06 -F



HNGX 06 -M



HNGX 06 -R



XNGX 06 ANSN

WENDESCHEIDPLATTEN (WSP) / INDEXABLE CUTTING INSERTS

ISO	Materialien / Grades									Abmessungen / Dimensions				
	M5315	M9315	M9325	M9340	M8310	M8340	8215	8230	8240	d	s	d ₁		
HNGX 0604ANSN-F				●	●	●	●	●	●	10,500	5,260	3,7		
HNGX 0604ANSN-M	●	●	●	●	●	●	●	●	●	10,500	5,260	3,7		
HNGX 0604ANSN-R	●	●	●		●	●	●	●	●	10,500	5,260	3,7		
XNGX 0604ANSN							●			10,500	5,260	3,7		

ERSATZTEILE / SPARE PARTS

*) Empfohlene Torxschraube – siehe Seite / For screw torques see pages: 394 – 397.

Fräser Marking of cutter	Spannschraube* Clamping screw*	Schraubendreher Screwdriver
SHN06	US 3007-T09P	Flag T09P